

LANCOM SFP Modules

	LANCOM SFP-LR-LC25	LANCOM SFP-LR-LC40	LANCOM SFP-SR-LC25	LANCOM SFP-SR-MPO40	LANCOM SFP-LX-LC1	LANCOM SFP-LX-LC10
Item number	60172	60174	60171	60173	61557	61497
Warranty	2 years	2 years	2 years	2 years	2 years	2 years
Compatible LANCOM devices	XS-6128QF	XS-5116QF XS-6128QF	XS-6128QF	XS-5116QF XS-6128QF	1790EF 1906VA series 1900EF GS-1326 GS-2310 series GS-2326+ series GS-2328 series GS-2352 series GS-3152X series GS-3528X series ISG-1000 ISG-4000 ISG-8000 R&S®UF-500 R&S®UF-9xx WLC-1000 XS-5116QF XS-6128QF	GS-2328 series GS-2352 series GS-3152X series GS-3528X series ISG-4000 ISG-8000 R&S®UF-500 R&S®UF-9xx XS-5110F XS-5116QF XS-6128QF

	LANCOM SFP-SX-LC1	LANCOM SFP-SX-LC10	LANCOM SFP-CO1	LANCOM SFP-CO10-MG	LANCOM SFP-DAC10-1M SFP-DAC10-3M	LANCOM SFP-DAC40-1M SFP-DAC40-3M
Item number	61556	61485	61494	60170	61495 (SFP-DAC10-1M) 60175 (SFP-DAC10-3M)	60176 (SFP-DAC40-1M) 60177 (SFP-DAC40-3M)
Warranty	2 years	2 years	2 years	2 years	2 years	2 years
Compatible LANCOM devices	1790EF 1900EF 1906VA series GS-1326 GS-2310 series GS-2326+ series GS-2328 series GS-2352 series GS-3152X series GS-3528X series ISG-1000 ISG-4000 ISG-8000 R&S®UF-500 R&S®UF-9xx WLC-1000 XS-5116QF XS-6128QF	GS-2328 series GS-2352 series GS-3152X series GS-3528X series ISG-4000 ISG-8000 R&S®UF-500 R&S®UF-9xx XS-5110F XS-5116QF XS-6128QF	GS-2328 series GS-2352 series Note: The module is not suitable for LANCOM GS-13xx, LANCOM 190x and LANCOM 2326x(+), as these products are equipped with combo ports. Hint: To use the LANCOM SFP-CO1 in a LANCOM switch requires at least LCOS SX 3.30 RU3.	GS-3152X series GS-3528X series XS-5110F XS-5116QF XS-6128QF	GS-2328 series* GS-2352 series* GS-3152X series GS-3528X series ISG-4000 ISG-8000 R&S®UF-500 R&S®UF-9xx XS-5110F XS-5116QF XS-6128QF * SFP-DAC10-1M only Hint: At least LCOS SX 3.30 RU3 is required to use the LANCOM SFP-DAC10 in a LANCOM switch.	XS-5116QF XS-6128QF Hint: At least LCOS SX 3.30 RU3 is required to use the LANCOM SFP-DAC40 in a LANCOM switch