

## Nokia G50

## **Specifications**

Design	<ul> <li>Colors Ocean Blue, Midnight Sun</li> <li>Size 173.86 x 77.6 x 8.85 mm</li> <li>Weight 220 g</li> </ul>
Performance	<ul> <li>Operating system Android 11 (Android One)</li> <li>RAM 4 GB</li> <li>Processor Qualcomm<sup>®</sup> Snapdragon<sup>™</sup> 480 5G Mobile Plattform</li> </ul>
Display	• 6.82" HD+ Display, 20.5:9, 720x1640
Connections and sensors	<ul> <li>Cable type USB type C (USB2.0)</li> <li>Sensors: Ambient light sensor, Proximity sensor, Accelerometer, E-compass, Fingerprint sensor, Gyro sensor,</li> <li>Single SIM or Dual SIM nano Slot + MicroSD (hybrid Slot)</li> </ul>
Network and connectivity	<ul> <li>Network speed 5G</li> <li>802.11 a/b/g/n/ac 2.4GHz + 5Ghz, Bluetooth<sup>®</sup> 5.0, GPS, AGPS, Galileo, Glonass, Beidou</li> <li>NFC</li> </ul>
Memory	<ul> <li>Internal memory 128 GB<sup>1</sup></li> <li>MicroSD card slot supports up to 512 GB</li> </ul>
Audio	<ul> <li>3.5 mm headphone jack</li> <li>2 microphones</li> <li>FM radio (headset required)</li> </ul>
Cameras	<ul> <li>Rear: 48 MP AF main camera, 5 MP ultra-wide, 2 MP Depth, Rear flash LED</li> <li>Front camera: 8 MP</li> </ul>
Battery	• 4850 mAh, Non removable
In the box	<ul> <li>Nokia G50, Charger, 1m USB type C, Quickstart Guide, Safety brochure, Protective Foil</li> </ul>







A powerful experience for entry-level smartphones. It's the best of Android, with new and revamped apps - and no bloatware.

© 2021 HMD Global. All rights reserved. HMD Global Oy is the exclusive licensee of the Nokia brand for phones and tablets. Nokia is a registered trademark of Nokia Corporation. Google and Android One™ are trademarks of Google LLC. All stated specifications, features and other product information are subject to change without notice. Qualcomm Snapdragon is a product of Qualcomm Technologies Inc. and/or its subsidiaries.

Pre-installed system software and apps consume a significant amount of memory.
 The battery has a limited number of charge cycles, so battery life will decrease over time. Sooner or later, the battery may need to be replaced.

