

# HP Mini Conference G9 PC with Microsoft Team Rooms (9C428AW)



## Specifications

<b>Operating system</b>	Windows 11 IoT Enterprise
<b>Processor family</b>	12th Generation Intel® Core™ i7 processor
<b>Processor</b>	Intel® Core™ i7-12700T (up to 4.7 GHz with Intel® Turbo Boost Technology, 25 MB L3 cache, 12 cores, 20 threads) [6,7]
<b>Memory</b>	16 GB DDR5-4800 MT/s (2 x 8 GB)
<b>Internal Storage</b>	256 GB PCIe® NVMe™ TLC SSD
<b>Graphics</b>	Integrated
<b>Graphics (integrated)</b>	Intel® UHD Graphics 770
<b>Wireless</b>	Intel® Wi-Fi 6E AX211 (2x2) and Bluetooth® 5.3 wireless card (supporting gigabit data rate)
<b>Power</b>	90 W external power adapter, up to 89% efficiency
<b>UPC number</b>	(AB0) 197961295788; (AB1) 197961295795; (AB2) 197961295771; (ABA) 197961295740; (ABB) 197961295825; (ABG) 197961295801; (ABJ) 4582712404520; (ABM) 197961295757; (ABT) 197961295856; (ABU) 197961295832; (AC4) 197961593150; (ACJ) 197961593143; (AR6) 197961295818; (UUF) 197961295764; (UUZ) 197961295863

## Top Recommended Displays, Accessories and Services

No Top Recommended Displays, Accessories and Services

## Messaging Footnotes

No Messaging Footnotes

## Technical Specifications Footnotes

[6] Multi-core is designed to improve performance of certain software products. Not all customers or software applications will necessarily benefit from use of this technology. Performance and clock frequency will vary depending on application workload and your hardware and software configurations. Intel's numbering, branding and/or naming is not a measurement of higher performance.

[7] Intel® Turbo Boost performance varies depending on hardware, software and overall system configuration. See <http://www.intel.com/technology/turboboost/> for more information.

---

© Copyright 2025 HP Development Company, L.P. The information contained herein is subject to change without notice. The only warranties for HP products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. HP shall not be liable for technical or editorial errors or omissions contained herein.

